

# TRANSPORTATION SAFETY

## DUMPERS




- 1. Pay special attention to the operating overhead crane while staying in the raw material warehouse.
- 2. Lower the trailer before leaving the unloading point.
- 3. Do not go under sliding material.
- 4. Do not enter on the semi trailer before unpacking without a security system.

## OTHER VEHICLES



- 1. Be cautious while working with equipment under pressure (protective eyewear, safe distance).
- 2. Use a safety system to protect yourself from falling down while staying on a silo-truck.
- 3. Climb up the tankers only on bays equipped with the protective systems.
- 4. Using wheel chocks is mandatory.

# REQUIRED CLOTHING



- 01. HELMET
- 02. PROTECTIVE GOGGLES  
To be used while loading/unloading cement or aluminium oxide
- 03. WARNING CLOTHING
- 04. LONG TROUSERS
- 05. WORKING FOOTWEAR

GÓRKA CEMENT

# Occupational Safety and Health Guide



Safety is most important to us. We believe that it is also important to our visitors. Therefore, we ask you to follow the guidelines contained in our guide.

# CORONAVIRUS

The main symptoms of the coronavirus disease include high fever, shortness of breath, cough, loss of smell or taste.

## How to prevent infection?



Wash your hands.



Cover your mouth and nose.



Keep 2-metre distance from other people.



Before entering the plant the temperature is measured and a health declaration is required.



If you show symptoms characteristic of COVID-19, contact a primary care physician over the phone. If human life or health is at risk, dial 112 or 999 emergency number immediately.

# IMPORTANT INFORMATION

Be cautious: there are hazards present in the area of the plant.



The site is under video surveillance for security purposes.



Follow the designated routes. If there are no routes, follow the edge of the road.



Watch out for forklift trucks.



Use the mandatory protective equipment.



Do not enter the overhead crane operation zone.



While working on a silo-truck, use the protective equipment for working at heights.



Do not run. Keep your hand out of your pockets.



Use wheel chocks (except for dumpers).



Smoking is prohibited except for designated places.



Stop only on the parking lot and at loading/unloading points.



Do not enter the production zones or closed areas without due authorisation.



When a hazard occurs, evacuate to the nearest exit.



Observe the maximum speed limit of 15 km/h.



Chemical substances – follow the instructions provided on the packaging.



Do not remove barriers and other protection



Do not drive with the door open

## Stanowiska załadunku cementu Loading points

- Załadunek cementów w workach i Big Bags**  
Loading of cement in bags and Big Bags
- Załadunek autocystemem cementem G40**  
Loading of silo-trucks with G40 cement
- Załadunek autocystemem cementem G70**  
Loading of silo-trucks with G70 cement
- Załadunek cementów w workach i Big Bags**  
Loading of cement in bags and Big Bags
- Załadunek autocystemem luzem**  
Loading of silo-trucks with bulk product
- Zawrót autocystemem G40**  
Return of the G40 silo-trucks
- Rozładunek tlenku – nad młyny**  
Alumina Oxide unloading – above the mills
- Rozładunek tlenku do silosów tlenku**  
Alumina Oxide unloading to oxide silos
- Załadunek dla drobnych odbiorców**  
Loading for small customers

- A** Dział Sprzedaży Sales Office
- B** Kierownik Zmiany Shift Manager
- Miejsce suszenia autocystemem Silo-Truck drying area
- Waga Weight
- Budynki Buildings
- Drogi zakładowe Internal road
- Drogi publiczne Public road
- Tory Railway tracks

