



TRANSPORTATION SAFETY



DUMPERS

1. Pay special attention to the operating overhead crane while staying in the raw material warehouse.
2. Lower the trailer before leaving the unloading point.
3. Do not go under sliding material.
4. Do not enter on the semi trailer before unpacking without a security system.



OTHER VEHICLES


1. Be cautious while working with equipment under pressure (protective eyewear, safe distance).
2. Use a safety system to protect yourself from falling down while staying on a silo-truck.
3. Climb up the tankers only on bays equipped with the protective systems.
4. Using wheel chocks is mandatory.



BE CAREFUL WHILE YOU APPROACH LOADING POINTS.

You may encounter other vehicles and elements of the plant's infrastructure, which are nearby.

REQUIRED CLOTHING



Clothes must be buttoned.

01. HELMET
02. PROTECTIVE GOGGLES
To be used while loading/unloading cement or aluminium oxide
03. WARNING CLOTHING
04. LONG TROUSERS
05. WORKING FOOTWEAR

GÓRKA CEMENT

Occupational Safety and Health Guide

Safety is most important to us. We believe that it is also important to our visitors. Therefore, we ask you to follow the guidelines contained in our guide.

Protect Your Eyes



There is a risk of eye injuries when unloading raw materials or loading cement. You must protect your eyes.

IMPORTANT INFORMATION

Be cautious: there are hazards present in the area of the plant.



The site is under video surveillance for security purposes.



Follow the designated routes. If there are no routes, follow the edge of the road.



Watch out for forklift trucks.



Use the mandatory protective equipment.



Do not enter the overhead crane operation zone.



While working on a silo-truck, use the protective equipment for working at heights.



Do not run. Keep your hand out of your pockets.



Use wheel chocks (except for dumpers).



Smoking is prohibited except for designated places.



Stop only on the parking lot and at loading/unloading points.



Do not enter the production zones or closed areas without due authorisation.



When a hazard occurs, evacuate to the nearest exit.



Observe the maximum speed limit of 15 km/h.



Chemical substances – follow the instructions provided on the packaging.



Do not remove barriers and other protection.



Do not drive with the door open.

CORONAVIRUS



Keep distance from other people.



Wash your hands.

Stanowiska załadunku cementu Loading points

- 1** Załadunek dla drobnych odbiorców
Loading for small customer
- 1A** Załadunek cementów w workach i BB
Loading of cement in bags and Big Bags
- 2** Załadunek autocystemem cementem G70
Loading of silo-trucks with G70 cement
- 3**
- 4** Załadunek cementów w workach i BB
Loading of cement in bags and Big Bags
- 4A**
- 5** Załadunek autocystemem luzem
Loading of silo-trucks with bulk product
- 6** Zawrót autocystemem G70
Return of the G70 silo-trucks
- 7** Rozładunek tlenku – nad młynny
Alumina Oxide unloading – above the mills
- 8** Rozładunek tlenku do silosów tlenku
Alumina Oxide unloading to oxide silos
- 9** Załadunek dla drobnych odbiorców
Loading for small customers
- 10** Załadunek cementów w workach i BB
Loading of cement in bags and Big Bags
- 11**

